



図5.2.7 初期掘削調査地点周辺土壌・地下水DPA汚染状況断面図



A南東90m (91~153ライン) (S=1:400)



A南東90m (92~154ライン) (S=1:400)

