







## 図5.2.8 初期掘削調査地点周辺土壤・地下水DPA A汚染状況図

<土壤>



<地下水>



DPA A濃度 (ppb)
不検出
● 1~ 10~
● 1000~ ● 10000~
● 100000~
● 100~