

たまには山へ恩返しin愛山溪 登山道整備講習会

資料2-5

日時:2019年8月19日(土)8:30~17:30


主催:環境省 上川自然保護官事務所

講師:北海道山岳整備 代表 岡崎哲三氏

場所:上川郡上川町愛山溪 愛山溪三十三曲~沼ノ平間の登山道

参加者:28名(山岳関係者、一般登山者)

※登山者にとって歩きやすい道にすることが、道脇の植生の保護につながる箇所で本講習会を実施。



1班

施工前	施工後
 A photograph showing a narrow, unpaved path made of small rocks and dirt, winding through dense green vegetation. The path is flanked by tall grasses and leafy plants. The ground is uneven and appears to be a natural or minimally cleared area.	 A photograph showing the same path after construction. The path is now wider and more defined, with a layer of larger stones and logs placed across it to reinforce the ground. A person in a green shirt is visible in the background, working on the path. The surrounding vegetation remains dense.

1班

施工前	施工後
	

2班

施工前	施工後
	

2班

施工前	施工後
	

2班

施工前	施工後
	

3班

施工前	施工後
	


3班

施工前	施工後
	

3班

施工前	施工後
 A photograph showing a steep, rocky slope before construction. The path is made of logs and stones, and the ground is uneven and rocky.	 A photograph showing the same slope after construction. The path is now more stable and finished, with logs and stones arranged in a more organized manner.

4班

施工前	施工後
	

4班

施工前	施工後
	

4班

施工前	施工後
	

4班

施工前	施工後
	

4班

施工前	施工後
 A photograph showing a dirt path leading up a hillside. A wooden log barrier runs across the path. To the right, a small stream flows. The path is surrounded by dense green vegetation.	 A photograph showing the same path after construction. The path is wider and more stable, with a wooden log barrier. The stream is now contained within a wooden structure. The path is surrounded by dense green vegetation.